

## Set-up Instructions



Always wear ANSI approved safety goggles when assembling this product.

**1** Remove all components from case and assist shock cords to straighten out and lock poles.

**2** Roll out banner on floor or carpet.



**3**

**4** Flex X-Leg slightly towards outside of graphic banner and insert end tip into banner pole hub.

**5** Insert X-Leg into banner pole hub.

**6** Secure the final corner into banner pole hub.

**7** Connect all corners together using "U" shape connector.




XtraFlex Hanging Sign Connex Kit



## Graphic Preparation Instructions

### Back of Graphic



### Bottom of Graphic

### Xtra Lite Warranty

## Hanging Kit - Set-up Instructions

Always wear ANSI approved safety goggles when assembling this product.



- 1 Use XtraFlex Connex "C" shaped connector to connect all three panels together. On the top connectors put on cable harness before connecting (as seen in photograph).



### **Xtra Lite Warranty**

Our X, S, T, E, M, P and B lines of frames come with a Lifetime Repair and Replace Warranty. If any of these frames break in the ordinary course of use, we will repair or replace the unit for \$10 per frame, or \$20 for roll-ups, plus return shipping. All other frames and accessories come with a One Year manufacturer's Limited Warranty against defects.

© 2004, Xtra Lite Display Systems, Inc. Xtra Lite®, Innovation for Results® and Mini-Lite® are registered trademarks of Xtra Lite Display Systems, Inc. All company, product, photos, logos and brand names are trademarks of their respective owners. Protected by one or more of the following U.S. and International Patents: #5,839,705, #6,012,688, #6,454,227. Other patents pending. Printed in USA. All rights reserved.